


Caution: The break-off pieces may fly off while twisting. Take reasonable precautions to prevent any flying pieces from causing injury.




Use 12mm screws.




Example 1

All break-offs removed.



Example 2

One break-off removed.



Break sections off as needed to expose connector.